PU 914-40 2K PU Hardener extra slow

Technical data sheet

Page 1 / 2



-	-	-	
Inte	nd	ad i	IICA

High Solid Hardener "extra slow" for Mipa 2K polyurethane acrylic paints and primers.

Processing instructions _



Mixing ratio hardener

by weight (lacquer : hardener) by volume (lacquer : hardener)

See basic product



Hardener



Pot life

See basic product



Thinner

See basic product



Processing viscosity

See basic product

Airmix/Airless gravity spray gun



Application mode

application mode	hardener	pressure (bar)	nozzle (mm)	spray passes	dilution
See basic product					



hardener	object temperature	dust dry	set to touch	ready for assembly	sandable	recoatable	
See basic product	-	-	_	-	_		

Note

Characteristics: binder base: Polyisocyanate

solids content (% by weight): ~ 55 solids content (% by volume): delivery viscosity DIN 53211 4 mm (in s): 17 - 19 density DIN EN ISO 2811 (kg/l): ~ 1,0

gloss level ISO 2813 at 60° (GU): See basic product

Properties: See basic product

Theoretical spreading rate: See basic product

PU 914-40 2K PU Hardener extra slow

Technical data sheet

Page 2 / 2



Storage: For at least 2 years in the unopened original container. Optimum storage conditions

between + 5 °C and + 25 °C, avoid direct sunlight. Other storage conditions may lead

to undesirable properties of the material.

VOC: See basic product

Processing conditions: See basic product

Substrate preparation: See basic product

Proposed coating structure: See basic product

Special notes: For professional use only.

Clean tools immediately after use with Mipa Nitroverdünnung.